


Install Manual

SDH-100-2000






Image for illustrative purposes only


Install



Base Mounting



Alarm (If Applicable)



Specifications

Electrical Specifications

Connection type		Shunt
Maximum backup fuse		63A

Mechanical Specifications

Minimum operating temperature		-40°C
Maximum operating temperature		85°C
Minimum operating humidity		5%
Maximum operating humidity		95%
Mounting method		Red Spot HRC fuse base
Environmental rating		IP20